



LOCTITE EA 9891RP AERO Epoxy Paste Adhesive (KNOWN AS Hysol EA 9891RP)

INTRODUCTION

LOCTITE EA 9891RP AERO is a two-component room temperature curing, abrasion resistant repair paste adhesive suitable for repairing LOCTITE® EF 9890 AERO abradable seal.

FEATURES

- Two-Component System
- Color Change on Mixing
- Abrasion Resistant
- Room Temperature Curing

Uncured Properties

	<u>Part A</u>	<u>Part B</u>	<u>Mixed</u>
Color	Black	Beige	Dark Gray
Density, lbs/ft ³	43	33	39
Density, g/ml	0.69	0.53	0.62
Shelf Life @ <82°F/28°C	1 year	1 year	

Handling

Mixing - This product requires mixing two components together just prior to application to the parts to be bonded. Long term storage may induce partial separation of the resins and fillers. Therefore, prior to use, bulk Part A and Part B should be inspected for separation. If separation is evident, mix each part thoroughly prior to mixing the Part A and Part B. Complete mixing is necessary.

<u>Mix Ratio</u>	<u>Part A</u>	<u>Part B</u>
By Weight	100	40

Note: Volume measurement is not recommended for structural applications unless special precautions are taken to assure proper ratios.

Pot Life (400 gram mass) 20 minutes @ 77°F/25°C
Method - ASTM D2471 in water bath.

Application

Mixing - Premix Part A prior to dispensing. Combine Part A and Part B in the correct ratio and mix thoroughly. THIS IS IMPORTANT! Heat buildup during or after mixing is normal. Do not mix quantities greater than 1.5 pounds/680 grams as dangerous heat buildup can occur causing uncontrolled decomposition of the mixed adhesive. WARNING! EXOTHERMIC – TOXIC FUMES CAN OCCUR, RESULTING IN PERSONAL INJURY. The adhesive should be used immediately to prevent a potentially dangerous heat buildup and subsequent uncontrolled decomposition of the mixed adhesive.





LOCTITE EA 9891RP AERO Epoxy Paste Adhesive (KNOWN AS Hysol EA 9891RP)

Applying - The area to be repaired should be clean, dry and properly prepared. Thin film set time for a 0.125 inch thick film adhesive will occur in 3 hours at 77°F/25°C, after which the support tooling or pressure used during cure may be removed.

Curing - This adhesive is sandable after curing 3 hours at 77°F/25°C. Full cure is attained after 24 hours at 77°F/25°C. A general guideline for determining when the material is sandable is to wait until the paste has a Shore D Hardness measurement of 60 or above. A heating blanket may be used to maintain 77°F/25°C temperatures, however, care must be taken to avoid a potential exotherm. The user needs to simulate repair conditions in order to develop the optimum heat and time cure profile for the specific repair.

Cleanup - It is important to remove excess adhesive from the work area and application equipment before it hardens. Denatured alcohol and many common industrial solvents are suitable for removing uncured adhesive. Consult your supplier's information pertaining to the safe and proper use of solvents.

Product Form - This product is available in 1.5 pound (680 grams) pint kits and 6 ounce (100 grams) barrier kits.

QC Acceptance Testing - Typical tests are Uncured and Cured Density, Shore D Hardness and Tension Strength tested at 77°F/25°C.

Bond Strength Performance

Tension Strength - tested per ASTM D638, type 1 after 24 hours cure at 77°F/25°C and 2 hours post cure at 160°F/71°C.

<u>Test Temperature, °F/°C</u>	<u>Environmental Soaks 7 days @ 77°F/25°C</u>	<u>Typical Results</u>	
		<u>psi</u>	<u>MPa</u>
77/25	-	1,650	11.4
	Skydrol Hydraulic Fluid	1,650	11.4
	Synthetic Lubrication Oil	1,650	11.4
160/71	-	525	3.6

Bulk Resin Properties

Shore D Hardness - tested per ASTM D2240, adhesive cure 24 hours @ 77°F/25°C plus 2 hours @ 160°F/71°C.

<u>Test Temperature, °F/°C</u>	<u>Typical Results</u>
77/25	65





LOCTITE EA 9891RP AERO

Epoxy Paste Adhesive

(KNOWN AS Hysol EA 9891RP)

General Instructions for Use

1. Hand sand area to be prepared to rough up the surface and to remove fluid/dirt contamination. Wipe with solvent after sanding to remove dust.
2. Mix entire components of either the pint or 6 oz barrier kit. Do not partially weigh out adhesive as potential separation of the components can adversely affect properties.
3. Thoroughly mix the adhesive until color and consistency is homogeneous, typically 4 to 5 minutes.
4. Apply adhesive to sanded area and smooth with trowel. To aid in adhesion and minimize slump, apply a nylon vacuum bag over the adhesive and work in thoroughly with a trowel. Leave the vacuum bag on until material is cured and then remove.
5. Allow to set for 3 hours at 77°F/25°C before sanding. Temperature below 77°F/25°C will require longer set times for full cure. As a general rule, each 18°F/10°C below 77°F/25°C will require twice the cure time.
6. Lightly sand front and rear edges of repair to improve air flow.

Handling Precautions

Do not handle or use until the Material Safety Data Sheet has been read and understood.
For industrial use only.

DISPOSAL INFORMATION

Dispose of spent remover and paint residue per local, state and regional regulations. Refer to HENKEL TECHNOLOGIES MATERIAL SAFETY DATA SHEET for additional disposal information.

PRECAUTIONARY INFORMATION

General:

As with most epoxy based systems, use this product with adequate ventilation. Do not get in eyes or on skin. Avoid breathing the vapors. Wash thoroughly with soap and water after handling. Empty containers retain product residue and vapors so obey all precautions when handling empty containers.

PART A

CAUTION! This material may cause eye and skin irritation or allergic dermatitis. It contains epoxy resins.

PART B

WARNING! This material causes eye and skin irritation or allergic dermatitis. It contains amines.

Before using this product refer to container label and HENKEL TECHNOLOGIES MATERIAL SAFETY DATA SHEET for additional precautionary, handling and first aid information.





Technical Process Bulletin

LOCTITE EA 9891RP AERO

Epoxy Paste Adhesive

(KNOWN AS Hysol EA 9891RP)

Note

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Loctite Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Loctite Corporation's products. Loctite Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.** The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Loctite Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

Rev. 7/2013

Henkel Corporation Aerospace | 2850 Willow Pass Road | Bay Point, CA 94565
PHONE: +1.925.458.8000 | FAX: +1.925.458.8030 | www.henkel.com/aerospace

Trademark usage

Except as otherwise noted, all trademarks in this document are trademarks of Henkel Corporation in the U.S. and elsewhere. ® denotes a trademark registered in the U.S. Patent and Trademark Office.

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Henkel Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Henkel Corporation's products. Henkel Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.** The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

